

Scope of Work at Landshut

Klasse	Kategorie	Einschränkung
MOTOREN Engines	B1 Turbine	Honeywell International Inc. LTS 101 Series ^{1) 2)}
	Turbine	Safran Helicopter Engines Arriel 1 ¹⁾
		Safran Helicopter Engines Arriel 2 ¹⁾

¹⁾ (Change of components and modules)

²⁾ (Maintenance of modules)

Klasse	Kategorie	ATA	Einschränkung
BAUTEILE Components	C6 Equipment	25-00	Winde <i>Hoist</i> 117-80403 und 117-804061 3HRL444301-10-4 3HRL444301-10-7 Goodrich 44301 Series
		25-67	EMS Ausrüstung <i>EMS Equipment</i> ARA-EC135-AC60 ARA-EC135-AC65 ARA-EC135-AC67 135710-502 ARA-BK117-AC40-7240 ARA-BK117-AC41 Aerolight BK117 C2-145060-501
			ARA-EC145-AC70 (Bucher) P/N: 1352-(Series)* 1353-(Series)* 1354-(Series)* 1361-(Series)* 1362-(Series)* 1363-(Series)* 1364-(Series)* 1365-(Series)*The authorization to use the combined number range (Series) is only valid as long as the - Maintenance procedure - Tool / Equipment - Qualification of authorized employees <u>DO NOT</u> differ significantly.
			Sitze Bestückung <i>Seat Equipment</i> Bucher P/N 1360100-100 Martin Baker P/N MBCS 6930-106 P/N MBCS 6930-110* * P/N change after Mod. (SB)
		25-11	Sitze <i>Seats</i> Fischer P/N 0520, 9506, 9507, 9613 Fischer Swiveling Unit 9715 0-2, 9715 1-2 und 9715 2-2

Scope of Work at Landshut ff

Klasse	Kategorie	ATA	Einschränkung
BAUTEILE Components	C7	71-64	IBF Filter (Left and Reight)
	Engine and APU		
			L716M2 X (Series) L716M1 X (Series) B716M1049xx B716M105xx